

Before Termarust



Before Termarust



After Termarust



After Termarust



Termarust coated crevice corroded structure after 2 years.

Termarust coated bearing after 7 years

Focus

Structure critical crevice corroded, pack rusted gusset plates, connections and corrosion frozen bearings

Opportunity

Save our deteriorating structural steel infrastructure with proactive coatings maintenance programs - to chemically stop corrosion

The Solution

Termarust's High Ratio Co-Polymerized Calcium Sulfonate chemically active TR2200LV Penetrant/Sealer and TR2100 Primer/Topcoat. This same formula has a 15 year field proven history of chemically stopping crevice corrosion and pack rust.

Visit our website for the whole story

www.termarust.com • toll free 1-888-279-5497

